

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Autotrail Arapaho SE
Reg Number - NO GAP	DF08JLF
HPI Clear	Yes
VAT	No
Engine Size	3.0
BHP	180
Transmission	Manual
Vehicle Weight (kg)	N/A
Miles or KM	Miles
Mileage	44936
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass


CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	No
More Info	Clutch slave
Clutch Slip Test Pass	No
More Info	Clutch slave
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	6
Belts	4
Bed Options	Overcab Bed, U Shape Rear
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	Yes
Further Info	Whole inside re-painted





CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, BBQ point, Front fog lights, Tow bar, Ladder, Bike Rack, Reversing camera, Tv Aerial
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Showing signs of age // front end wrapped



Any Damage Found	Yes
Damage Further Info	Heavy damage to NS // previous repair to NSR roof







Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection


Internal Extras	Alarm, cab A/C, Cab blinds, Carpets, Cruise control, Tv(s), Leather, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Paint finish damage in areas // roof centre board fitted // roof rear trim glued





Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Slight soft around OSR arch
Floor damp/spongy/damaged	Yes
Floor Info	2 areas of delamination - rear U shape and next to forward facing belted seats in kitchen



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	None
Cam belt changed	No
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Fail
Test Drive Details	No clutch
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Andrew Rowe
Sign-off Date	2026-01-19