

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Swift Escape 624
Reg Number - NO GAP	FN63SYA
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3300
Miles or KM	Miles
Mileage	71847
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	No
Notes	Cab seats non standard // fridge changed // woodwork modified in places
Berths	4
Belts	4
Bed Options	Bench Seats
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A





CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Air Suspension, Alloys, Awning, BBQ point, Bike Rack, Reversing camera, Tow bar, Gaslow, Satellite dish, Solar panel, Tv Aerial
Other External Extras	N/A
Decals	Need attention
Decals Further Info	NS bonnet decal flake



Any Damage Found	Yes
Damage Further Info	OS dent // OSR small dents behind cassette locker // NSR corner damage // NS locker door changed // dent to OS o/cab // NSR high level // crease to front of OS dinette window // leisure battery's reboxed







Windscreen

Crack



Alloy Wheels

Good

Tyres illegal/cracking/out of date

No

Electric Step

Fully Working

Self levelling work

N/A


Pop top canvas damage

N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Bluetooth, Cab blinds, Oven, Tv(s), Climate control, Diesel heater, Upgraded stereo
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Wood work / displays modified // cab seats aftermarket // areas of wood finish damage





Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Staining and pimpling in roof behind centre skylight // stain in NS high level wall above cupboards // staining in both OS locker doors // light stains behind front edge of NS bench cushions
Floor damp/spongy/damaged	Yes
Floor Info	Small area of swelling in floor behind Hab door step





Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Andrew Rowe
Sign-off Date	2026-06-04