

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Burstner Lyseo Harmony TD 734
Reg Number - NO GAP	HX18DMU
HPI Clear	Yes
VAT	No
Engine Size	2.3L
BHP	148
Transmission	Manual
Vehicle Weight (kg)	4T
Miles or KM	Miles
Mileage	27966
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	No
More Info	Coolant level low
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	3
Belts	4
Bed Options	Island Bed, Bench Seats
Lounge Layout	Two Forward Facing, Half Dinette
Layout Correct	Yes
Further Comments	N/A


CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Alloys, BBQ point, Electric step, Front fog lights, Gaslow, Reversing camera, Solar panel
Decals	Need attention
Decals Further Info	NS decals very fine cracking



Any Damage Found	Yes
Damage Further Info	Crease above off side garage door // Rust spot on drivers door // two small dents on NS lower panel // Scratch on off side skirt near rear wheel



Windscreen	No damage
------------	-----------

Alloy Wheels	Need attention
Alloy Further Info	All four showing oxidation



Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Cab blinds, Bluetooth, Cruise control, Hill descent control, Leather, Oven, Traction control plus
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	No





Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Full
Service Info	Log book photo,d
Cam belt changed	Yes
Cam belt info	See pic above
Habitation service reports	Partial
Habitation Info	Last service photo,d



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-03-13