

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Sunseeker 200
Reg Number - NO GAP	WJ06GBE
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	100
Transmission	Manual
Vehicle Weight (kg)	3400
Miles or KM	Miles
Mileage	40308
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	1
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	2
Bed Options	U Shape Rear, Overcab Bed
Lounge Layout	U-Shaped Rear Lounge
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Bike Rack, Reversing camera, Tow bar, Manual step, Tv Aerial
Decals	Need attention
Decals Further Info	Age related fading



Any Damage Found	Yes
Damage Further Info	OSF scuff // paint peel to bonnet // scattered small dents on either side // Delamination on O/S // Rust on tow bar // end cap of awning is missing // Damage to NSF top corner




Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection






Internal Extras	Cab curtains, Awning (Porch or Safari), Oven, Upgraded stereo
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Paper shrink around windows // paper dropped on overcab roof // rip on floor mat on driver side



Damp Inspection

Damp (visible/soft)	Yes
---------------------	-----


Floor damp/spongy/damaged	Yes
Floor Info	Floor damaged under OS bench to outer edge // floor slightly swollen around entry step



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	One invoice 2021
Cam belt changed	No
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	Yes
Engine Lights Info	Service light
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Andrew Rowe
Sign-off Date	2026-02-05