

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Autoquest 130
Reg Number - NO GAP	YN08OYM
HPI Clear	Yes
VAT	No
Engine Size	2.2L
BHP	100
Transmission	Manual
Vehicle Weight (kg)	3.5T
Miles or KM	Miles
Mileage	42216
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	No
More Info	Coolant level low light on dash
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	Yes
More Info	Slight surge Engine tappity when idling

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Overcab Bed, Bench Seats
Lounge Layout	Bench Seats, Two Forward Facing
Layout Correct	Yes
Further Comments	N/A


CMS MOTORHOME INSPECTION FORM

Exterior Inspection


External Extras	Awning, Bike Rack, Manual step, Habitation door lock
Decals	Need attention
Decals Further Info	Fading and delamination



Any Damage Found	Yes
Damage Further Info	<p>Near side bottom of Bumper cracked Dent on near side (Hab door damage) Stone chips on near side door Bonnet well out of line Scratch on Bonnet Scratches just behind drivers door Paint peel on column behind drivers door plus dents Rust bubbling both in front and behind off side wheel Poor sealant on bottom edge of bumper off side</p>








Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Cab curtains, Multifunction steering wheel, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Hand brake damaged (bent) // Drivers armrest damaged // Lamination on side of off side Bench seat // Passenger side recliner control broken off // Rippled wallpaper in bathroom





Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Discoloured under window
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	None
Cam belt changed	No
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-02-15