

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Autosleeper Orian Aquillas
Reg Number - NO GAP	MX55UWU
HPI Clear	Yes
VAT	No
Engine Size	2.8
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	23880
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	1
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	6
Belts	4
Bed Options	Overcab Bed, French Bed
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Ladder, Bike Rack, Solar panel, Electric step, Awning, Tv Aerial, Reversing camera, Air Suspension
Decals	Need attention
Decals Further Info	Age related fading & perishing



Any Damage Found	Yes
Damage Further Info	Paint peel on bonnet // Hab door clip broken // gas point flap replaced // OSR lower damage // OS rear window broken // water fill cap missing





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	Dated 2015 // no perishing

Electric Step	Not Working
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Upgraded stereo, Oven, Tv(s), Cab curtains
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Table painted // sink top missing



### Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Staining in roof to rear OS of big skylight // staining to roof NSF // staining in lower OS dinette fabric under window
Floor damp/spongy/damaged	Yes
Floor Info	Floor delaminated in most of walkway





