

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Geist Matterhorn
Reg Number - NO GAP	PO55LUF
HPI Clear	Yes
VAT	Yes
Engine Size	2.7
BHP	150
Transmission	Manual
Vehicle Weight (kg)	4600
Miles or KM	Miles
Mileage	36820
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	6
Belts	4
Bed Options	Transverse Bed, Overcab Bed
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Electric step, Ladder, Reversing camera, Roof rack, Tv Aerial, Bike Rack, Tow bar
Other External Extras	N/A
Decals	Need attention
Decals Further Info	N/A



Any Damage Found	Yes
Damage Further Info	OSR impact // OSR top garage catch loose // small paint mark behind Hab door







Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Upgraded stereo, Oven, Cab curtains, Tv(s), Carpets, Alarm
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Damage to dinette table // dinette area cushions frayed // cab seats covered





Damp Inspection

Damp (visible/soft)	Yes
Damp Info	OS dinette window lower rear corner rotten 99% // watermarks around lower corners of most window but low reading 6-14% // slightly stained in rear high level cupboards but low reading 14% // mark to NSF corner of front skylight but low reading // light staining to rear of bathroom skylight
Floor damp/spongy/damaged	No





CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	None
Cam belt changed	N/A
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Andrew Rowe
Sign-off Date	2026-05-12