

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Lunar Cassini EB
Reg Number - NO GAP	PO68EFU
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3800
Miles or KM	Miles
Mileage	13380
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Twin Beds Over Garage, Bench Seats
Lounge Layout	Half Dinette, Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

Vehicle Profile Photos (Front, Rear & Both Sides):



External Extras	Awning, BBQ point, Electric step, Reversing camera, Solar panel, Parking sensors, Tv Aerial
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Lifting on some corners of the decals



Any Damage Found	Yes
Damage Further Info	Dent ns to left of hab door // ns rear corner crack// high scratch on off side above window



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM




Internal Inspection

Internal Extras	Alarm, Cab blinds, cab A/C, Bluetooth, Carpets, Cruise control, DAB radio, Multifunction steering wheel, Oven, Sat nav
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Stains in ceiling above hab door ceiling and wall high readings , side of hab door, rear off side corner and ceiling blue stain. Bathroom floor high read in and off side garage floor
Floor damp/spongy/damaged	Yes
Floor Info	Soft in bathroom floor and os garage floor non visible






CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Full
Service Info	4 services
Date of Last Engine Service	19/08/25
Cam belt changed	No
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Jonathan Hayreh
Sign-off Date	2026-07-07

