

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Roller Team Auto-Roller 600
Reg Number - NO GAP	WA08CCF
HPI Clear	Yes
VAT	No
Engine Size	2.4litre
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500 kg
Miles or KM	Miles
Mileage	29916
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout



Does internal look original?	No
Notes	Kitchen and back wall have been refinished
Berths	6
Belts	6
Bed Options	Bench Seats, Overcab Bed
Lounge Layout	Full Dinette, Bench Seats, U-Shaped Rear Lounge
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Bike Rack, Air Suspension, Habitation door lock, Tow bar, Solar panel, Tv Aerial
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	<p>Poor repair to rear of vehicle Scratches to rear of vehicle off side Gouge in bodywork above rear window off side Hab door handle badly discoloured Rust bottom of drivers door Ford badge ruined on front Scratches near side above rear wheel Damage near side rear light cluster Damage around reverse camera on rear of vehicle</p>





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A

Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM


Internal Inspection

Internal Extras	Bluetooth, Multifunction steering wheel, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Roof completely repainted Vent warped



Damp Inspection

Damp (visible/soft)	Yes
Damp Info	99 reading with poor repair around roof fan 99 reading just behind over cab bed wall paper swollen and dimpled 99 reading and swollen wallpaper off side over cab bed wall paper 99 both rear corners
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	None
Cam belt changed	No
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-05-14