

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	CI Carioca 625
Reg Number - NO GAP	YN54VZB
HPI Clear	Yes
VAT	No
Engine Size	2300cc
BHP	120
Transmission	Manual
Vehicle Weight (kg)	3400kg
Miles or KM	Miles
Mileage	49980
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	5
Belts	4
Bed Options	Bench Seats, Overcab Bed
Lounge Layout	Two Forward Facing, Half Dinette
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Bike Rack, Ladder, Electric step, Habitation door lock
Other External Extras	N/A
Decals	Need attention
Decals Further Info	In reasonable condition however bonnet decals been removed New set inside vehicle needs putting on
Any Damage Found	Yes
Damage Further Info	Off side wing mirror damaged Poor repair under drivers window Two holes under vent near side Poor repair off side rear corner Off side window damaged and poorly repaired Poor repair near side rear bumper
Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	Too flat and dirty to assess
Electric Step	Not Working, Step is Damaged
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Tv(s), Upgraded stereo
Other Extras	N/A
Electrics turn on	No
More Info	Suspected flat leisure battery
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Gear stick cover missing Off side window cracked

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Nearside wall over cab bed soft and high readings Rear half of roof high readings Rear wall in high lockers soft and high readings Rot around locker door under n/s Bench seat all Nearside wall soft spot and high readings All along Window rotten around washroom window
Floor damp/spongy/damaged	Yes
Floor Info	Floor rippled under near side Bench seat And off side Bench seat

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	None
Cam belt changed	No
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Fail
Test Drive Details	Vehicle being recovered
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-05-15