

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Elddis Autoquest 400
Reg Number - NO GAP	EU05BCZ
HPI Clear	Yes
VAT	No
Engine Size	2.2 litre
BHP	101 bhp
Transmission	Manual
Vehicle Weight (kg)	3500 kg
Miles or KM	Miles
Mileage	47552
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	No
More Info	Clutch is completely useless
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	4
Belts	2
Bed Options	Bench Seats, Overcab Bed
Lounge Layout	U-Shaped Rear Lounge, Bench Seats
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Awning, Bike Rack, Manual step, Reversing camera, Solar panel, Tow bar, Tv Aerial
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Fading due to age



Any Damage Found	Yes
Damage Further Info	<p>Poor repair on near side front panel          Near side wing mirror cracked          Cracking on near side pillar behind door          Hab door damaged barely closes          Air vent damaged held on with tape          Rear wheel arch damaged near side pillar behind          Bottom skirt broken near side rear corner          Bike rack been moved causing damage          Dents to rear          Damage to off side rear corner          Rippling on off side panel behind door          Paint peeling on drivers door          Front bumper damaged on off          Side          Ariel broken          Age related bumps and scratches</p>







Windscreen

Chip(s) smaller than 10p



Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	No
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Cab curtains, Carpets, Oven, Tv(s)
Other Extras	N/A
Electrics turn on	No
More Info	No electrics suspected flat leisure battery
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	No

### Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Red staining on roof with 99 readings Blue staining and 99 readings on top of wash room wall
Floor damp/spongy/damaged	No





## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	No
Engine Service History	None
Cam belt changed	No
Habitation service reports	None

### Test Drive & Sign Off

Test drive - 10 mins	Fail
Test Drive Details	Couldn't do test drive due to clutch failure
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-04-16