

CMS MOTORHOME INSPECTION FORM

General

CMS Motorhome Inspection	
Make & Model	
Reg Number - NO GAP	
HPI Clear	
Engine Size	
BHP	
Transmission	
Miles or KM	
Mileage	
Confirm miles (within 5,000)	
Is Mileage Warranted	
How many sets of engine keys	
V5 present	
Does the V5 vin match 2 x Vehicle vins	

Engine Bay

Are fluid levels correct? oil/coolant/brake fluid	
More Info	
Engine bay check	
More info	

External Inspection


External Extras	
Any Other Extras	
Decals	
Further Info	
Decal Photos	
Any Damage Found	
Further Information	

CMS MOTORHOME INSPECTION FORM


Damage Photos




CMS MOTORHOME INSPECTION FORM



CMS MOTORHOME INSPECTION FORM



CMS MOTORHOME INSPECTION FORM



CMS MOTORHOME INSPECTION FORM



Windscreen

Damage Photos

CMS MOTORHOME INSPECTION FORM

Alloy Wheels	
Further Information	
Damage Photos	
Are the tyres illegal, cracking or out of date (6 years)	
Further Info	
Tyre photos	
Electric Step	
Does self levelling work? (if applicable)	
Further comments	
Further Photo's	
Further info	

Internal layout

Berths	
Belts	
Lounge	
Bed options	
Layout correct	
Further Comments	
Multi Photo	
Further info	

Internal Inspection

Internal Extras	
Other extras	
Do the electrics turn on	
More info	
Control Panel Damaged? Screen/buttons	
More Info	
Does the stereo turn on	
Smell or signs of smoking	
Are all cushions correct including travel cushions	
Is the boiler present	

CMS MOTORHOME INSPECTION FORM

Are overhead lockers empty/objects secure ready for travel?	
Damage	
Damage info	
Damage photos	

Damp inspection

Damp (visible/Soft)	
Damp info	
Photos of any damp	
Floor damp/spongey/damaged	
Further info	
Floor photos	

Paperwork

Manuals present	
Engine Service History	
Engine Service info	

CMS MOTORHOME INSPECTION FORM

Engine Service photos

PHILLIPS OF WORMLEY
Petworth Road, Wormley, Godalming, GU8 5TU
TEL: 01428 682104 - EMAIL: email@phillipsofwormley.com

VAT Number 709 1639 28
Bank Details: Lloyds Bank - Sort Code 30-93-49 Account Number 00729630

Mr Baker 10 Brook Meadow Chiddingfold Godalming GU8 4UZ	Date 09/08/23 Oper DH Customer Acc Number BAK010 Customer Ord Number Our Reference Number J 3064568
---	--

Page 1 of 1

GDPR Data: All data which is held by us is stored on a secure database and can only be accessed by us. We do not pass your details onto third parties and is not used in marketing by us. If you wish not to be contacted by us, by post, email or text message i.e. MOT and service reminders please contact us.

Description	Qty	Price	Vat
Work Carried Out			
Carry out Annual Service.	2.25	78.00	17
Carry out brake fluid change	1.00	40.00	4
Fit new oil pressure switch.	0.50	78.00	
Supply and fit 3 new tyres			
Items Used			
1735047 Oil filter	1.00	6.81	
30 Fully Synthetic engine oil litre C2	4.25	7.99	
545079 Fuel filter	1.00	11.79	
Wash	1.00	0.10	
Wash and clutch fluid Dot 4	1.00	5.15	
70049 Oil pressure switch	1.00	16.74	
5 CR90/88T Hilfy S2000 Van tyre	3.00	52.95	
Wheel	3.00	5.00	
3 Tyre Valve	3.00	2.50	
Waste disposal of tyre.	3.00	3.50	

Date	Goods	Vat	Payment Summary		Goods & Services	
0.00%	520.90	104.18			Goods & Services	
					Total Net Amount	
					Total VAT Amount	

Vehicle Details

Cost Breakdown

CMS MOTORHOME INSPECTION FORM

Petworth Road, Wormley
TEL: 01428 682104 - EMAIL: email@phm...
VAT Number 709 1639 28
Bank Details: Lloyds Bank - Sort Code 30-93-49 Account Number 00729630

Date 09/08/23 Oper DH
Customer Acc Number BAK010
Customer Ord Number
Our Reference Number J 3064568

Mr Baker
10 Brook Meadow
Chiddingfold
Godalming
GU8 4UZ

Page 1 of

FIRST ROUTINE SERVICE : ALL VEHICLES

Normal Severe

STANDARD OPERATIONS To be carried out systematically

REPLACE:

- Pollen filter (if fitted)
- Diesel fuel filter (TD and HDI)
- Sparking plugs (CS 2.0 HP)
- Pressure reducer filter on Relay CNG
- LPG electrovalve filter (Savo and Berlingo)
- Electrovalve filters (Relay LPG)
- Air filter on Relay 2.8HD

GENERAL OPERATIONS Every 37,500/40,000 miles.

CHECKS:

- Calipers, discs and brake pipes
- Wear of rear brake linings (if there are inspection plugs)
- Sealing of dampers
- Tension of accessory drive belts, if not fitted with automatic tensioner
- Valve clearances (Relay LPG)
- Play in hubs, link rods, ball joints and articulations

REPLACE:

- Sparking plugs (except V6)
- Air filter (except Relay 2.8TD, 2.8HDI)
- Diesel fuel filter
- Petrol filter (except C2, C3, C5 and C8)

OPERATIONS ACCORDING TO AGE

REPLACE:

- Brake fluid (2 years) or LHM and clean filter (5 years)
- Inspect and pressure test CNG, LPG reservoir (France) 8 years, 5 years if vehicle sold)

SPECIFIC OPERATIONS According to equipment

DIESEL:

- 1 Saxo 1.5D: Replace Diesel fuel filter
- 2 C2, C3 and Xsara 1.4HDI: Outside W.Europe (except overseas France and central and eastern Europe): Replace air filter

PETROL:

- 1 V6: Replace sparking plugs
- 2 Outside W.Europe (except overseas France and central and eastern Europe): Replace fuel filter on C5 and C8
- 3 Outside W.Europe (except overseas France and central and eastern Europe): Replace fuel filter on C3 and C2

PARTICLE FILTER:

- 1 Replace particle filter with a standard exchange and top up with Eolys fluid

RELAY:

- 1 Petrol, TDI, HDI: Replace engine coolant
- 2 TDI: Replace air filter
- 3 Check valve clearances

TIMING BELT

- REPLACE: Timing belt

1st routine service
Mileage 4040
Job N°: 4927
Date: 6.3.06

STAMP OF THE SERVICING DEALER

UD Biarmall
38 STAMFORD RD
KETERING
NORTHANTS
NN16 8LJ
TEL: (01603) 810338

Vehicle Details	Cost Breakdown
Registration AE05HHP	LABOUR 254.50
CITROEN	PARTS 266.40
BERLINGO 800D LX	
16/05/2005	
	Total VAT Amount
	Total Amount Due

CMS MOTORHOME INSPECTION FORM

PHILLIPS OF WORMLEY
Phillips of Wormley, Godalming, GU8 5TU
Petworth Road, Wormley, Godalming, GU8 5TU
TEL: 01428 662104 - EMAIL: email@phillipsofwormley.com
VAT Number 709 1639 28
VAT Code 30-93-49 Account Number 00729630

Bank Details: Lloyds Bank - Sort Code 30-93-49

Date: 09/08/23 Oper: DH BAK010
Customer Acc Number: BAK010
Customer Ord Number: J 3064568
Our Reference Number: J 3064568

Mr Baker
10 Brook Meadow
Godalming
GU8 4UZ

ROUTINE SERVICING

Stamp of the Servicing Dealer:
Evars Halshaw
38 STAMFORD ROAD
KETERING
NORTHANTS
NN16 8LJ
TEL: (01538) 310333
FAX: (01538) 523373

2nd routine service
Mileage: 10355
Job No: 10710
Date: 9/5/07

PHILLIPS OF WORMLEY
Phillips of Wormley, Godalming, GU8 5TU
Petworth Road, Wormley, Godalming, GU8 5TU
TEL: 01428 662104 - EMAIL: email@phillipsofwormley.com
VAT Number 709 1639 28
VAT Code 30-93-49 Account Number 00729630

Bank Details: Lloyds Bank - Sort Code 30-93-49

Date: 09/08/23 Oper: DH BAK010
Customer Acc Number: BAK010
Customer Ord Number: J 3064568
Our Reference Number: J 3064568


Mr Baker
10 Brook Meadow
Godalming
GU8 4UZ

ROUTINE SERVICING

Stamp of the Servicing Dealer:
Evars Halshaw
38 STAMFORD ROAD
KETERING
NORTHANTS
NN16 8LJ
TEL: (01538) 310333
FAX: (01538) 523373

3rd routine service
Mileage: 14,080
Job No: 15392
Date: 28/4/08

CMS MOTORHOME INSPECTION FORM



CMS MOTORHOME INSPECTION FORM

TH ROUTINE SERVICE: ALL VEHICLES Normal Severe

SPECIFIC OPERATIONS According to equipment

DIESEL:

- Replace Diesel fuel filter
- CS, C3 and Xsara 1.4HD: Replace Diesel fuel filter
- Outside W.Europe (except overseas France and central and eastern Europe): Replace air filter

PETROL:

- WB: Replace sparking plugs
- Outside W.Europe (except overseas France and central and eastern Europe): Replace fuel filter on C3 and C2
- Outside W.Europe: Replace fuel filter on C3 and C2

PARTICLE FILTER:

- Replace particle filter with a standard exchange and top up with Ecolys fluid

REPLACEMENT:

- TDI, HDI: Replace engine coolant
- TDI: Replace air filter
- Check valve clearances

TIMING BELT

REPLACE: Timing belt

Stamp: **STAMP OF THE SERVICING DEALER**
MOTORHOMES LTD
MCA APPROVED
01554 05177

Job N: 24524
Date: 3-5-13

9th routine service
Mileage 24524

Stamp: **STAMP OF THE SERVICING DEALER**
Evans Halshaw service
Kettering
NN16 8LJ
01536 31038
enquiries@evanshalshaw.com

Job N 37455
Date: 3/5/13

Stamp: **STAMP OF THE SERVICING DEALER**
Evans Halshaw service
Kettering
NN16 8LJ
01536 31038
enquiries@evanshalshaw.com

Stamp: **STAMP OF THE SERVICING DEALER**
Evans Halshaw service
Kettering
NN16 8LJ
01536 31038
enquiries@evanshalshaw.com

CMS MOTORHOME INSPECTION FORM

10th ROUTINE SERVICE: ALL VEHICLES

Normal Severe

SPECIFIC OPERATIONS According to equipment

DIESEL:

- Saco 1.8D: Replace Diesel fuel filter
- C2, C3 and Xaura 1.4HD: Outside W.Europe (except overseas France and central and eastern Europe): Replace air filter

PETROL:

- Replace sparking plugs
- Outside W.Europe (except overseas France and central and eastern Europe): Replace fuel filter on C5 and C2
- Outside W.Europe: Replace fuel filter on C5 and C2

PARTICLE FILTER:

- Replace particle filter with a standard exchange and top up with Ecolife fluid

RELAY:

- Petrol, TD, HD: Replace engine coolant
- TD: Replace air filter
- Check valve clearances

TIMING BELT:

- REPLACE: Timing belt

10th routine service
Mileage: 25241
Job N°: 23-1-14
Date: 23-1-14

STAMP OF THE SERVICING DEALER
CENTRE LTD
APPROVED
SOUTH-WELFORD
ASH ESTTT

LABOUR PARTS

13th ROUTINE SERVICE: ALL VEHICLES

Normal Severe

SPECIFIC OPERATIONS According to equipment

DIESEL:

- Saco 1.8D: Replace Diesel fuel filter
- C2, C3 and Xaura 1.4HD: Outside W.Europe (except overseas France and central and eastern Europe): Replace air filter

PETROL:

- Replace sparking plugs
- Outside W.Europe (except overseas France and central and eastern Europe): Replace fuel filter on C5 and C2
- Outside W.Europe: Replace fuel filter on C5 and C2

PARTICLE FILTER:

- Replace particle filter with a standard exchange and top up with Ecolife fluid

RELAY:

- Petrol, TD, HD: Replace engine coolant
- TD: Replace air filter
- Check valve clearances

TIMING BELT:

- REPLACE: Timing belt

11th routine service
Mileage: 37443
Job N°: AMR
Date: 14/1/25

STAMP OF THE SERVICING DEALER
Morgan
APPROVED
SOUTH-WELFORD
ASH ESTTT

LABOUR PARTS

CMS MOTORHOME INSPECTION FORM

<p>Has the cam belt been changed? (5 years on all ford 2.0 and fiat 2.3)</p>	
<p>Cam belt change info</p>	

CMS MOTORHOME INSPECTION FORM

Cam belt change invoice

PHILLIPS OF WORMLEY			Petworth Road, Wormley, Godalming, GU8 5TU			TEL: 01428 682104 - EMAIL: email@phillipsofwormley.com		
VAT Number 709 1639 28			Bank Details: Lloyds Bank - Sort Code 30-93-49 Account Number 00729630			Page 1 of 1		
Mr Baker 10 Brook Meadow Chiddingfold, Godalming GU8 4UZ			Date	12/03/24	Oper	DH		
			Customer Acc Number	BAK010				
			Customer Ord Number					
			Our Reference Number	J 3065803				
<p>GDPR Data: All data which is held by us is stored on a secure database and can only be accessed by us. We do not pass your details onto third parties and is not used in marketing by us. If you wish not to be contacted by us, by post, email or text message i.e. MOT and service reminders please contact us.</p>								
Description	Qty	Price	Value					
Work Carried Out								
Replace cam belt, tensioner, guide pulley and water pump.	4.00	78.00	312.00					
Check all tyre pressures								
Parts Used								
INAS30044010 Cam belt kit	1.00	72.87	72.87					
BOS6PK1440 Auxiliary drive belt	1.00	24.20	24.20					
GRFPA747 Water pump	1.00	45.20	45.20					
Blue Anti-Freeze	3.00	5.32	15.96					
204120039 Header tank cap	1.00	9.05	9.05					
Rate			Goods	Vat	Payment Summary			
20.00%			479.28	95.85				
					Goods & Services			
					Goods & Services 479.28			
					Total Net Amount 479.28			
					Total VAT Amount 95.85			
					Total Amount Due 575.13			
Vehicle Details			Cost Breakdown					
tion	AE05HHP			LABOUR	312.00			
	CITROEN			PARTS	167.28			
	BERLINGO 800D LX							
	16/05/2005							
	51.431							

Habitation Service Reports

Habitation service info

Habitation service photos

Test drive

Test drive - 10 mins

Further details

Engine lights

Further info

Dashboard Ghosting

CMS MOTORHOME INSPECTION FORM

Sign off

Completed by	
Date/Time	
<p>In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit https://www.bca.co.uk for auction terms and conditions. Bid at your own risk.</p>	