

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Chaussan Flash 03
Reg Number - NO GAP	KL08PZB
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	130
Transmission	Manual
Miles or KM	Miles
Mileage	28934
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	6
Belts	4
Bed Options	Overcab Bed, Bench Seats, Bunk Beds
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	No

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Bike Rack, Reversing camera, Tv Aerial
Decals	Need attention
Decals Further Info	I damaged, but faded



Any Damage Found	Yes
Damage Further Info	Paint flaking on hinges of garage & gas locker// Rear nearside plastic trim cracked & repaired//



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Cab curtains, Carpets, Cruise control, Diesel heater, Multifunction steering wheel, Oven, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Full
Service Info	Service stamps in book 2009,2010,2011,2012,2014,2015,2016,2018 Invoices for services in 2024,2025 Customer states other services have been done & records will be available at Ramir services
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	No reports or paperwork, but stamps 2012,2014,2015



+1 more photo(s) available



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	D4119
Completed by	Tim Craner
Sign-off Date	2025-09-24
Price Guide	N/A