

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Elddis Autoquest 120
Reg Number - NO GAP	AU61DRX
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	100
Transmission	Manual
Vehicle Weight (kg)	3000
Miles or KM	Miles
Mileage	25602
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	U Shape Rear
Lounge Layout	U-Shaped Rear Lounge
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection


Vehicle Profile Photos (Front, Rear & Both Sides):



External Extras	Awning, Electric step, Habitation door lock, Tow bar, Reversing camera, Tv Aerial, Solar panel
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Small dents on OSR



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No



Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Multifunction steering wheel, Oven, Cab curtains, Carpets
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

### Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Staining in roof above Hab door leading into cupboard roof // swelling in high level bathroom wall // bathroom & wardrobe roof painted // cassette locker door swollen
Floor damp/spongy/damaged	No







## CMS MOTORHOME INSPECTION FORM



### Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	7 stamps
Date of Last Engine Service	24/09/24 @ 23873
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	2 reports
Date of Last Habitation Service	27/09/24





## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Andrew Rowe
Sign-off Date	2026-06-24