

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Sunseeker 100
Reg Number - NO GAP	KX55HLG
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	100
Transmission	Manual
Vehicle Weight (kg)	2900
Miles or KM	Miles
Mileage	49974
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	1
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	5
Belts	4
Bed Options	Overcab Bed, Bench Seats
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection


External Extras	Bike Rack, Manual step
Decals	Need attention
Decals Further Info	Faded



Any Damage Found	Yes
Damage Further Info	Paint peel on ns door Broken ns mirror Ns rust bubble Ding in hab door Os rear corner dent Os rust bubble Crease next to scratch window os



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	Both front tires scrubbing on inner edges




Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Cab curtains, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Plastic surround on internal hab step broken Broken over cab blind All walls have sticky backed paper which is rippled on all walls





Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	June 25
Cam belt changed	No
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Jonathan Hayreh
Sign-off Date	2026-04-23