

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Lunik Conversion
Reg Number - NO GAP	BA23JVD
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	130
Transmission	Manual
Miles or KM	Miles
Mileage	11847
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	No

CMS MOTORHOME INSPECTION FORM


Exterior Inspection

External Extras	Alloys, Reversing camera, Parking sensors, Solar panel, LED daytime running lights
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Slight scratch ns wing // scuff marks ns lower bumper // slight scuff marks above os front tire // slight scratch drivers door // scuff marks on rear door // scuff marks nsr // scratch hab door //



+5 more photo(s) available

Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	N/A





+1 more photo(s) available

Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, Multifunction steering wheel, cab A/C, Bluetooth, Sat nav, DAB radio
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	No
Boiler present	Yes
Overhead lockers ready	No
Internal Damage	Yes
Damage Info	Slight felt peel // dink on cupboard door //



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	None
Cam belt changed	N/A
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	K4044
Completed by	Keenan Parnell
Sign-off Date	2025-09-18
Price Guide	N/A