

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Devon Aztec
Reg Number - NO GAP	BF16HWT
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	130
Transmission	Manual
Miles or KM	Miles
Mileage	55520
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	1
V5 present	No
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	U Shape Rear
Lounge Layout	U-Shaped Rear Lounge
Layout Correct	Yes
Further Comments	No

CMS MOTORHOME INSPECTION FORM


Exterior Inspection

External Extras	Alloys, Gaslow, Parking sensors, Tv Aerial
Decals	Good
Any Damage Found	Yes
Damage Further Info	Rear o/s door post dented // Rear n/s door post dented // rear door dented // n/s rear sill damage // habitation step missing



+3 more photo(s) available

Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	N/r cracking no date stamp



Damp floor underneath	No
Electric Step	Not Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, cab A/C, Cruise control, DAB radio, Multifunction steering wheel, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Shower tray needs resealing // head liner dropping to front // hole in rear door // hab door panels coming off



+2 more photo(s) available

Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Last service 15/02/23
Cam belt changed	No
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	L7059
Completed by	Rodger Snell
Sign-off Date	2025-08-28
Price Guide	N/A