

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Pilote Sensation P710
Reg Number - NO GAP	BV16TVO
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3650
Miles or KM	Miles
Mileage	19059
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	5
Bed Options	French Bed, Bench Seats, Twin Beds Over Garage
Lounge Layout	Half Dinette, Bench Seats
Layout Correct	Yes
Further Comments	N/A



CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Front fog lights, LED daytime running lights, Reversing camera, Bike Rack, Electric step, Solar panel, Tv Aerial
Decals	Need attention
Decals Further Info	Rear decals are ripped slightly // O/S decal behind driver door rippled



Any Damage Found	Yes
Damage Further Info	Rust on wiper arm // Small dink on bonnet // Light scuff on N/S window frame //






Windscreen	Chip(s) smaller than 10p
------------	--------------------------



Alloy Wheels	N/A
--------------	-----

Tyres illegal/cracking/out of date	Yes
------------------------------------	-----

Tyre Further Info	Both O/S tyres are dated 2015 - but good condition
-------------------	--



Electric Step	Fully Working
---------------	---------------

Self levelling work	N/A
---------------------	-----

Pop top canvas damage	N/A
-----------------------	-----

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, Bluetooth, cab A/C, Cab blinds, Carpets, Cruise control, Oven, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	No
Internal Damage	Yes
Damage Info	Entrance slightly scuffed



Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Small area of staining on O/S wall in overhead locker
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Latest: 2023
Cam belt changed	No
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Leigh Ireland
Sign-off Date	2026-03-12