

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Swift Sundance 530LP
Reg Number - NO GAP	BX06NUA
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	85
Transmission	Manual
Vehicle Weight (kg)	3000
Miles or KM	Miles
Mileage	38124
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	1
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Alloys, Awning, Bike Rack, Electric step, Tv Aerial, Solar panel, Reversing camera, Habitation door lock
Decals	Need attention
Decals Further Info	Overcab decal faded



Any Damage Found	Yes
Damage Further Info	Small areas of paint peel on bonnet and driver door // Dinks on NS overcab // NS window skin is peeling // Chip OSR bumper corner







Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM


### Internal Inspection

Internal Extras	Alarm, Cab blinds, Oven, Tv(s), Cab curtains
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No



### Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Blue staining on roof near cupboard and into bathroom roof // Overplate on cupboard roof // Soft and stained around flue
Floor damp/spongy/damaged	No






## CMS MOTORHOME INSPECTION FORM



### Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Latest: 05/10/2020
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	Latest: 08/10/2024 KO





## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	No
Completed by	Leigh Ireland
Sign-off Date	2026-04-16