

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Adria Coral XI Plus 670 DK
Reg Number - NO GAP	BX18LWJ
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	127
Transmission	Manual
Miles or KM	Miles
Mileage	16212
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	7
Belts	7
Bed Options	Bench Seats, Overcab Bed, Bunk Beds
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	No

CMS MOTORHOME INSPECTION FORM


Exterior Inspection

External Extras	Awning, Alloys, BBQ point, Bike Rack, Electric step, Front fog lights, Habitation door lock, Gaslow, LED daytime running lights, Parking sensors, Reversing camera, Solar panel, Tv Aerial, Ladder, Shower point
Decals	Need attention
Decals Further Info	Slight paint flake between bumper & wing panel on front offside // Small area of peeled decal on rear nearside & top rear & offside behind drivers door




+3 more photo(s) available

Any Damage Found	Yes
Damage Further Info	Very small ding on bottom of drivers door // Small scratch rear offside corner, level with top of garage door



Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	Oxidation on both rear wheels



Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, Bluetooth, cab A/C, Cab blinds, Carpets, Cruise control, DAB radio, Hill descent control, Multifunction steering wheel, Oven, Part leather, Sat nav, tracker, Traction control plus, WIFI
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	No
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No


Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Service invoices for 2019 & 2023
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	Habitation services for 2019,2022,2023,2024,2025



+5 more photo(s) available

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	K4044
Completed by	Tim Craner
Sign-off Date	2025-10-09
Price Guide	N/A