

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Swift Escape 644
Reg Number - NO GAP	BX66VYK
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3300
Miles or KM	Miles
Mileage	23987
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Overcab Bed, U Shape Rear
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

Vehicle Profile Photos (Front, Rear & Both Sides):



External Extras	Bike Rack, Electric step, Shower point, Reversing camera, Tv Aerial, Solar panel
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Scuff/knock to NSR // Damage to OSR corner // Small scratch centre front grill // Dinks to NSR corner





Windscreen

Chip(s) smaller than 10p



Alloy Wheels

N/A

Tyres illegal/cracking/out of date

No

Electric Step

Fully Working

Self levelling work

N/A



Pop top canvas damage

N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, cab A/C, Cab blinds, Carpets, DAB radio, Oven, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	O/s kitchen window inner skin stress crack // N/s overcab window damage/cracks around handle



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No


CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Full with this owner since 2019
Date of Last Engine Service	29/06/26
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	N/A
Date of Last Habitation Service	03/06/26



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-07-08