

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elevating Roof Company Conversions
Reg Number - NO GAP	YE66XYB
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	188
Transmission	Automatic
Vehicle Weight (kg)	3050
Miles or KM	Miles
Mileage	68807
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	No
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

Vehicle Profile Photos (Front, Rear & Both Sides):



External Extras	Alloys, Front fog lights, Parking sensors, Solar panel, Tow bar, Reversing camera
Other External Extras	N/A
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Small stone chips on bonnet Both door mirror casing scuffed Small dink on NS above fuel cap small scuff n/s bumper corner Light scuff NSF



Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Climate control, Bluetooth, Cruise control, Multifunction steering wheel, Leather, Sat nav, Diesel heater, Lithium battery, Other (inc accessories), Carpets
Other Extras	3000w inverter
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No


CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Three reports
Date of Last Engine Service	10/08/2021
Cam belt changed	No
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	No
Completed by	Leigh Ireland
Sign-off Date	2026-07-03

