

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Swift Escape 694
Reg Number - NO GAP	BX17LFF
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	127
Transmission	Manual
Vehicle Weight (kg)	3650
Miles or KM	Miles
Mileage	17773
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	6
Belts	5
Bed Options	Bench Seats, Drop Down Bed, Island Bed
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Bike Rack, Parking sensors, Tv Aerial, Solar panel
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Peeling to decals on over cab



Any Damage Found	Yes
Damage Further Info	Paint discoloured and small crease on NS // Stone chips NSF





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Carpets, cab A/C, Cab blinds, Auto headlights, Cruise control, DAB radio, Multifunction steering wheel, Oven, Bluetooth
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Small dent in n/s wall rear // Stain on mattress



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

Sign-off Date	2026-06-08