

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Adria Coral 660SL
Reg Number - NO GAP	CN58DWE
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	46020
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	3
Belts	5
Bed Options	Twin Beds Over Garage, Bench Seats
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A



CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Satellite dish, Tv Aerial, Reversing camera
Other External Extras	N/A
Decals	Need attention
Decals Further Info	not original decals and a picture on rear panel



Any Damage Found	Yes
Damage Further Info	Paint flaking multiple areas on the cab, bonnet/wings/ a pillars and doors







Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, cab A/C, Cab blinds, Bluetooth, DAB radio, Sat nav, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Table top marked but repaired, one blind damaged, cupboard door won't lock



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Feb 26
Date of Last Engine Service	N/A
Cam belt changed	Yes
Cam belt info	Feb 26
Habitation service reports	Partial
Habitation Info	September 25
Date of Last Habitation Service	N/A

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Jonathan Hayreh
Sign-off Date	2026-03-27