

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Dream Tech Conversions
Reg Number - NO GAP	DA17CZB
HPI Clear	Yes
VAT	No
Engine Size	1.6
BHP	125
Transmission	Manual
Miles or KM	Miles
Mileage	60848
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



Internal Layout

Does internal look original?	Yes
Berths	4
Belts	5
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	No

CMS MOTORHOME INSPECTION FORM



Exterior Inspection

External Extras	Alloys, Front fog lights, Reversing camera, Solar panel
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Stone chips on bonnet // Scratch on fuel cap // Scratch on sliding door // Dent on rear door // Flaking on O/S/R corner // Small dink on O/S panel



+3 more photo(s) available

Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	N/S/F and N/S/R slight scuffs



Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Other (inc accessories), cab A/C, Leather, Cruise control, Multifunction steering wheel
Other Extras	1000w inverter
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	One of the light covers has fallen - it's in glovebox


Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Full
Service Info	FSH Latest: 27/03/2025
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	One: 19/04/2024



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	L7057
Completed by	Leigh
Sign-off Date	2025-09-18
Price Guide	N/A