

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Universal Customs
Reg Number - NO GAP	DF70GZZ
HPI Clear	Yes
VAT	No
Engine Size	1968
BHP	109
Transmission	Manual
Vehicle Weight (kg)	2800
Miles or KM	Miles
Mileage	25773
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	1
V5 present	No
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Campervan
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Gaslow, Parking sensors, Reversing camera, Front fog lights, Solar panel, BBQ point
Decals	N/A
Any Damage Found	No
Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Auto headlights, cab A/C, Cruise control, DAB radio, Bluetooth, Diesel heater, Multifunction steering wheel, WIFI, Climate control
Other Extras	Pull down blinds on all habitation windows
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Service invoice 2024 service in 2025 & additional oil & filter service in 2025
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	One report dated 15/02/25



