

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Burstner Delfin T821
Reg Number - NO GAP	DX57HYC
HPI Clear	Yes
VAT	No
Engine Size	2.5
BHP	80
Transmission	Manual
Vehicle Weight (kg)	4500
Miles or KM	Miles
Mileage	54876
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Transverse Bed
Lounge Layout	Half Dinette, Bench Seats
Layout Correct	Yes
Further Comments	N/A


CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Electric step, Ladder, Reversing camera, Tv Aerial, Solar panel, Roof rack
Decals	Good
Any Damage Found	Yes
Damage Further Info	Slight scuff on cluster // few dinks on top // slight crease on //



Windscreen	Chip(s) smaller than 10p
------------	--------------------------



Alloy Wheels	N/A
--------------	-----

Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM



Internal Inspection

Internal Extras	Carpets, Cab blinds, cab A/C, Bluetooth, DAB radio, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Stained blind //



Damp Inspection

Damp (visible/soft)	Yes
Damp Info	High readings and stained ceiling os above kitchen // stained around the skylight none reading
Floor damp/spongy/damaged	No





CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	11/11/2015
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	28/11/2014



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	Yes

V5 tested on DVLA	Yes
Completed by	Keenan Parnell
Sign-off Date	2026-04-20