

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Auto Trail Tracker EKS
Reg Number - NO GAP	FH18JCY
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	118
Transmission	Manual
Vehicle Weight (kg)	3.5
Miles or KM	Miles
Mileage	13299
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A


CMS MOTORHOME INSPECTION FORM


Exterior Inspection

External Extras	Awning, Electric step, LED daytime running lights, Reversing camera, Solar panel, Tow bar, Tv Aerial
Decals	Good
Any Damage Found	Yes
Damage Further Info	Scratch to near side front bumper



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	Tyres all cracking





Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A



CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, cab A/C, Cab blinds, Carpets, Cruise control, Hill descent control, Multifunction steering wheel, Oven, Tv(s), Traction control plus, Sat nav
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	small amount of blue staining around OS wheel arch under boiler cover
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Last service shown
Cam belt changed	Yes
Cam belt info	Proof shown
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	Yes
Engine Lights Info	General yellow warning light
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-03-03

