

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	WildAx Constellation
Reg Number - NO GAP	FH54TXA
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	103
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	121144
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	1
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	No
More Info	Power steering fluid low - corroded pipes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	Yes
More Info	Heavy steering
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	5
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM


Exterior Inspection

External Extras	Awning, Bike Rack
Decals	Need attention
Decals Further Info	Faded



Any Damage Found	Yes
Damage Further Info	Paint flake on rear, o/s front upper corner. Bonnet stone chips, door dented o/s, sill rusty o/s. Paint bubble o/s few touch ups to the rear





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A

Self levelling work	N/A
Pop top canvas damage	N/A


CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Upgraded stereo, Oven, Bluetooth
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Floor under o/s bench seat reading 40's and soft
Floor damp/spongy/damaged	Yes
Floor Info	See above damp section




CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Paperwork for all previous services
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	N/A



Test Drive & Sign Off

Test drive - 10 mins	Fail
Test Drive Details	Power steering heavy
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Daryl
Sign-off Date	2026-02-18

