

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Auto-Trail Frontier Dakota
Reg Number - NO GAP	FJ17CVR
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	150
Transmission	Manual
Vehicle Weight (kg)	4500
Miles or KM	Miles
Mileage	25174
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


### Internal Layout

Does internal look original?	Yes
Berths	4
Belts	2
Bed Options	Bench Seats, French Bed
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM





### Exterior Inspection

External Extras	BBQ point, Alloys, LED daytime running lights, Electric step, Parking sensors, Reversing camera, Tow bar, Satellite dish, Solar panel, Shower point, Awning
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Dent on habitation door // deep scratch on bumper // scratch on bonnet // Overcab lettering peeling away





Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	Scratches



Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Alarm, cab A/C, Cab blinds, Carpets, Cruise control, Hill descent control, Multifunction steering wheel, Oven, Traction control plus, Tv(s), Bluetooth, DAB radio, Sat nav, tracker
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No







### Damp Inspection





Damp (visible/soft)	No
Floor damp/spongy/damaged	No

# CMS MOTORHOME INSPECTION FORM

## Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	One missing
Date of Last Engine Service	12/06/25
Cam belt changed	Yes
Cam belt info	27/10/22
Habitation service reports	Partial
Habitation Info	Invoiced
Date of Last Habitation Service	09/03/26





## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	David Walker
Sign-off Date	2026-05-27