

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Hymer Yosemite
Reg Number - NO GAP	FN69XHU
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Automatic
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	28709
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Transverse Bed, Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A


CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, LED daytime running lights, Gaslow, Front fog lights, Electric step, Solar panel, Parking sensors, Reversing camera, Tow bar
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Scratch on rear door // small dent n/s //



Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	Front o/s scored





Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	Yes
Pop Top Damage Info	Small tear



CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Bluetooth, Cab blinds, Cruise control, DAB radio, Hill descent control, Sat nav, tracker, Traction control plus
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Staining to pop top roof // trim on step re-glued // stain under n/s side window




Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Three stamps, last service 28/08/25
Date of Last Engine Service	N/A
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	Invoiced
Date of Last Habitation Service	N/A



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	David Walker
Sign-off Date	2026-05-14