

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Autosleeper Vivanti 4S
Reg Number - NO GAP	FX04WMY
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	84
Transmission	Manual
Miles or KM	Miles
Mileage	61680
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	5
Belts	4
Bed Options	Overcab Bed, Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	No

## CMS MOTORHOME INSPECTION FORM

## Exterior Inspection

External Extras	Awning, Tow bar, Tv Aerial, Reversing camera
Decals	Need attention
Decals Further Info	Showing signs of age in places



Any Damage Found	Yes
Damage Further Info	Lower plastics crazing in places // stone chips to bonnet



+1 more photo(s) available

Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	Dated 2017 // no perishing and lots of tread



Damp floor underneath	Yes
Damp Further Info	NS and OS rears rotting
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A




## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Bluetooth, Cab curtains, DAB radio, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Front skylight siliconed shut // damaged heater top // tile stickers in kitchen area // cracks to plastics in bathroom // dents to inner Hab door



+3 more photo(s) available




### Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Light Pimpling around NS window // swollen area in bathroom rear wall
Floor damp/spongy/damaged	Yes
Floor Info	NSR corner rotten // slightly soft throughout



+1 more photo(s) available



## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
Engine Service History	Full
Service Info	Fully stamped book, just missing 25
Cam belt changed	No
Habitation service reports	None



### Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	K4044
Completed by	Andrew Rowe
Sign-off Date	2025-09-30
Price Guide	Off