

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Rapido Le Randonneur 7066F
Reg Number - NO GAP	FX09CBO
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3700
Miles or KM	Miles
Mileage	55885
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Bench Seats, Twin Beds Over Garage
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A



CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Bike Rack, Reversing camera, LED daytime running lights, Solar panel, Tv Aerial, Roof rack
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Overcab decal peeling slightly



Any Damage Found	Yes
Damage Further Info	Paint peel NS of front windscreen // Small crack on NSR wheel arch





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Cab blinds, Cab curtains, Carpets, Cruise control, Heated mirrors, Bluetooth
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Top locker o/s rear
Floor damp/spongy/damaged	No






CMS MOTORHOME INSPECTION FORM



Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	N/A
Date of Last Engine Service	26/4/24
Cam belt changed	Yes
Cam belt info	25/7/24
Habitation service reports	Partial
Habitation Info	N/A
Date of Last Habitation Service	19/7/25





Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Rodger Snell
Sign-off Date	2026-06-11