

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Auto-Trail Tracker EKS
Reg Number - NO GAP	FY69RFN
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	140
Transmission	9 Speed Automatic
Vehicle Weight (kg)	3650
Miles or KM	Miles
Mileage	10967
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

Vehicle Profile Photos (Front, Rear & Both Sides):



External Extras	Alloys, Awning, LED daytime running lights, Electric step, Reversing camera, Solar panel, Satellite dish
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Damage to OSR corner at top





Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	All 2019 and in good condition
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, Bluetooth, cab A/C, Cab blinds, Carpets, Cruise control, DAB radio, Sat nav, Part leather, Oven, Multifunction steering wheel, Lithium battery, Hill descent control, Traction control plus, Tv(s), Other (inc accessories)
Other Extras	1000W inverter
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Floor lino ripped under sink // Wodden box stuck down on work top





Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	4 stamps
Date of Last Engine Service	15/08/2025
Cam belt changed	Yes
Cam belt info	15/08/2025
Habitation service reports	Partial
Habitation Info	2 reports
Date of Last Habitation Service	03/11/2025



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Leigh Ireland
Sign-off Date	2026-06-15