

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	VW Bilbo Celeste
Reg Number - NO GAP	GF53PCZ
HPI Clear	Yes
VAT	No
Engine Size	2.5
BHP	102
Transmission	Manual
Vehicle Weight (kg)	2620
Miles or KM	Miles
Mileage	100461
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



Internal Layout


Does internal look original?	Yes
Berths	2
Belts	5
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Tow bar, Front fog lights
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Dent on drivers door // faded paintwork // n/s headlight + indicator condensation rusting on n/s roof





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	None
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	No



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	No
Engine Service History	Partial
Service Info	Last one 21-5-2025
Cam belt changed	No
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Fail
Test Drive Details	Gearbox issues
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	No
Completed by	David Walker
Sign-off Date	2026-04-06