

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	The Campervan Factory
Reg Number - NO GAP	GK68TKD
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	195
Transmission	Manual
Vehicle Weight (kg)	2800
Miles or KM	Miles
Mileage	68569
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	No
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	4
Belts	5
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Alloys, Awning, Front fog lights, Parking sensors, Tow bar
Other External Extras	N/A
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Scratch drivers door // front bumper scuffs-scratches // light scratches down n/s // dent and scratches on rear door // rear bumper cracked // pop top rear scratched





Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Auto headlights, Bluetooth, cab A/C, DAB radio, Cruise control, Diesel heater, Heated mirrors, Multifunction steering wheel
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Rear seat belts stained - ripped // front seats stained // drivers seat ripped // fridge dented



### Damp Inspection

Damp (visible/soft)	No
---------------------	----



## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	All invoiced
Date of Last Engine Service	21/05/2025
Cam belt changed	Yes
Cam belt info	Changed 10/01/2023
Habitation service reports	None

### Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	David Walker
Sign-off Date	2026-05-12