

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Romahome Hylø
Reg Number - NO GAP	GN06AUW
HPI Clear	Yes
VAT	No
Engine Size	1.9
BHP	70
Transmission	Manual
Vehicle Weight (kg)	2850
Miles or KM	Miles
Mileage	28362
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	4
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Parking sensors
Decals	N/A
Any Damage Found	No
Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, cab A/C, Cab curtains, Upgraded stereo, Diesel heater
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	No
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Last one 7-4-25
Cam belt changed	Yes
Cam belt info	14-5-24
Habitation service reports	Partial
Habitation Info	Last one 23-10-24

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	David Walker
Sign-off Date	2026-03-12