

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Murvi Morello
Reg Number - NO GAP	GU04FXK
HPI Clear	Yes
VAT	No
Engine Size	2.8
BHP	127
Transmission	Manual
Vehicle Weight (kg)	3300
Miles or KM	Miles
Mileage	58912
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	2
Belts	5
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Tv Aerial, BBQ point
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Paint fade on grill // roof rail cover coming off // dent to rear n/s post top // dent to o/s post rear top // scratches to o/s





Windscreen	No damage
Alloy Wheels	

N/A	
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Diesel heater, Cab curtains, Heated mirrors, Upgraded stereo
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Sink is loose // bathroom ceiling broken up // seating faded // bathroom door lock u/s // gas bottles in a none lined cupboard// open back to fridge and cooker // bathroom window lining needs replacing//





## Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Rear door and bathroom roof
Floor damp/spongy/damaged	Yes
Floor Info	Soft around hab door





## CMS MOTORHOME INSPECTION FORM




### Paperwork

Manuals present	Yes
-----------------	-----






Engine Service History	Partial
Service Info	Stamps in book 2005 every year to 2015 except 2007 Invoices for 2015,2017 every year to 2024
Date of Last Engine Service	18/10/2024
Cam belt changed	Yes
Cam belt info	27/11/2012 at 42126 miles 29/04/2016 at 46813 miles
Habitation service reports	None









## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Rodger Snell
Sign-off Date	2026-06-05