

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Autotrail Arapaho
Reg Number - NO GAP	GX06CGK
HPI Clear	Yes
VAT	No
Engine Size	2.8
BHP	130
Transmission	Manual
Miles or KM	Miles
Mileage	39219
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	6
Belts	6
Bed Options	Overcab Bed, U Shape Rear
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	No

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Alloys, Tv Aerial, Tow bar, Reversing camera, Ladder, Awning, Electric step, Front fog lights, Satellite dome, Solar panel
Decals	Good
Any Damage Found	Yes
Damage Further Info	Tiny hole on rear // impact to number plate surround // paint peel on drivers door and scratch-dent // passenger door paint peel //



+2 more photo(s) available

Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	2 on OS starting to perish



Damp floor underneath	No
Electric Step	Step is loose
Self levelling work	No
Pop top canvas damage	No

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Carpets, Diesel heater, Oven, Upgraded stereo, Alarm, Cab curtains
Other Extras	N/A
Electrics turn on	No
More Info	Leisure battery disconnected
Control panel damaged	Yes
More Info	Beeping
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Staining to U shape rear fabrics



### Damp Inspection

Damp (visible/soft)	Yes
Damp Info	High level kitchen wall in cupboard swollen & soft // areas of staining in roof // both rear arches light staining in walls
Floor damp/spongy/damaged	No



+2 more photo(s) available

## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Latest 24 with clutch done too
Cam belt changed	N/A
Habitation service reports	None



### Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	L7058
Completed by	Andrew Rowe
Sign-off Date	2025-12-03
Price Guide	N/A