

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Bailey Approach 740 SE
Reg Number - NO GAP	HX12KTA
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	29432
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



Internal Layout

Does internal look original?	Yes
Berths	4
Belts	2
Bed Options	Bench Seats, French Bed
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Habitation door lock, Reversing camera, Tv Aerial, Solar panel, Front fog lights
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Paint flake to n/s A post // crack to over cab // small dent in bonnet // head light covers discoloured//



Windscreen	Chip(s) smaller than 10p
------------	--------------------------



Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Auto headlights, cab A/C, Cruise control, Cab blinds, Heated mirrors, Part leather, Multifunction steering wheel, Oven, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Vinyl on floor is ripped



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No


CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Full
Service Info	20/2/25
Date of Last Engine Service	N/A
Cam belt changed	N/A
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Rodger Snell
Sign-off Date	2026-05-26

