

CMS MOTORHOME INSPECTION FORM

General

CMS Motorhome Inspection	
Make & Model	
Reg Number - NO GAP	
HPI Clear	
Engine Size	
BHP	
Transmission	
Miles or KM	
Mileage	
Confirm miles (within 5,000)	
Is Mileage Warranted	
How many sets of engine keys	
V5 present	
Does the V5 vin match 2 x Vehicle vins	

Engine Bay

Are fluid levels correct? oil/coolant/brake fluid	
More Info	
Engine bay check	
More info	

External Inspection

External Extras	
Any Other Extras	
Decals	
Further Info	
Decal Photos	
Any Damage Found	
Further Information	

CMS MOTORHOME INSPECTION FORM


Damage Photos



CMS MOTORHOME INSPECTION FORM



CMS MOTORHOME INSPECTION FORM

	
Windscreen	
Damage Photos	

CMS MOTORHOME INSPECTION FORM

Alloy Wheels	
Further Information	
Damage Photos	
Are the tyres illegal, cracking or out of date (6 years)	
Further Info	
Tyre photos	
Electric Step	
Does self levelling work? (if applicable)	
Further comments	
Further Photo's	
Further info	

Internal layout

Berths	
Belts	
Lounge	
Bed options	
Layout correct	
Further Comments	
Multi Photo	
Further info	


Internal Inspection

Internal Extras	
Other extras	
Do the electrics turn on	
More info	
Control Panel Damaged? Screen/buttons	
More Info	
Does the stereo turn on	
Smell or signs of smoking	
Are all cushions correct including travel cushions	
Is the boiler present	

CMS MOTORHOME INSPECTION FORM

Are overhead lockers empty/objects secure ready for travel?	
Damage	
Damage info	
Damage photos	

Damp inspection

Damp (visible/Soft)	
Damp info	
Photos of any damp	

CMS MOTORHOME INSPECTION FORM




Floor damp/spongey/damaged	
Further info	
Floor photos	

Paperwork

Manuals present	
Engine Service History	

CMS MOTORHOME INSPECTION FORM

Engine Service info																																																																		
Engine Service photos	 <p>DETAILS</p> <p>Retail J/N 247961 Date 26/03/2024 Order no Customer Advisor A.Ashforth</p> <p>VEHICLE Registration HX15 DFC Make Elddis Model Majestic 115 Spec Motorhome[2 Berth]2 Chassis No. VF3YBUMAU12680599 Engine No TRJA0764196 Fabrication No Reg Date 24/03/2015 Warranty Exp Mileage In 22704 Out 22711 Colour White Engine Size 2198 Transmission Manual Service Due 24/03/2025 MOT Due 04/04/2025</p> <p>Vehicle Booked in for : Date In 26/03/2024 STOCK Time In 10:00 Pre Delivery Inspection Date Req MOT Time Req 10:00 Service Required Car Sales VHC Requested by: ashley MOT MOT</p> <p>Repair : A</p> <p>Comment :</p> <table border="1"> <thead> <tr> <th>Item</th> <th>Person</th> <th>Rate</th> <th>Qty</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>Carried Out Vehicle Identity Check Including Print of VIN &</td> <td>Darrel J</td> <td>65.00</td> <td>0.40</td> <td>£26.00</td> </tr> <tr> <td>PDI</td> <td>Darrel J</td> <td>65.00</td> <td>2.00</td> <td>£130.00</td> </tr> <tr> <td>SERVICE</td> <td>Darrel J</td> <td>65.00</td> <td>0.50</td> <td>£32.50</td> </tr> <tr> <td>VHC</td> <td>Darrel J</td> <td>0.00</td> <td>0.30</td> <td>£0.00</td> </tr> <tr> <td>MOT Labour</td> <td>Mike E</td> <td>65.00</td> <td>0.75</td> <td>£0.00</td> </tr> <tr> <td>Carried Out MOT Test</td> <td>Mike E</td> <td>65.00</td> <td>0.8</td> <td>£0.00</td> </tr> </tbody> </table> <p>Parts/Materials</p> <table border="1"> <thead> <tr> <th>Part Number</th> <th>Description</th> <th>Qty</th> <th>Retail</th> <th>Price</th> <th>Total Price</th> </tr> </thead> <tbody> <tr> <td></td> <td>#NPANST6269 TIE ROD END</td> <td>1.00</td> <td></td> <td>£17.53</td> <td>£17.53</td> </tr> <tr> <td>SX75/90</td> <td>GEAR OIL SYNTHETIC</td> <td>0.20</td> <td>£9.50</td> <td>£5.06</td> <td>£1.01</td> </tr> <tr> <td>2128722</td> <td>OIL FILTER</td> <td>1.00</td> <td>£17.44</td> <td>£8.63</td> <td>£8.63</td> </tr> <tr> <td>EOIL</td> <td>F 913D 5W/30 ENGINE OIL</td> <td>6.10</td> <td>£9.95</td> <td>£5.95</td> <td>£36.30</td> </tr> </tbody> </table> <p>Repair Totals: Total Labour: £188.50 Total Parts: £63.47 Repair Total: £251.97</p> <p>Work Carried Out: Carried Out Vehicle Identity Check Including Print of VIN & Any Fault Codes Listed. CARRIED OUT VISUAL HEALTH CHECK / PDI CARRY OUT OIL AND FILTER SERVICE CHECKED LIGHTS GREASED DOORS CHECKED COOLANT TEMP SET (-32C) CHECKED BRAKES - FRONT BRAKES 15% WORN - REAR BRAKES 15% WORN REPLACED NS TIE ROD END FREE OFF HANDBRAKE LEVER PIVOT POINTS TYRE DEPTH NSF. 7 OSF. 7 NSR. 8 OSR. 8 SPARE.10 CHECKED LEVELS & TOPPED UP SCREENWASH TORQUED WHEELS TO 160 NM ROADTESTED ALL OK CARRY OUT MOT TEST PASS 577152452909 EXP 04/04/25</p>	Item	Person	Rate	Qty	Total	Carried Out Vehicle Identity Check Including Print of VIN &	Darrel J	65.00	0.40	£26.00	PDI	Darrel J	65.00	2.00	£130.00	SERVICE	Darrel J	65.00	0.50	£32.50	VHC	Darrel J	0.00	0.30	£0.00	MOT Labour	Mike E	65.00	0.75	£0.00	Carried Out MOT Test	Mike E	65.00	0.8	£0.00	Part Number	Description	Qty	Retail	Price	Total Price		#NPANST6269 TIE ROD END	1.00		£17.53	£17.53	SX75/90	GEAR OIL SYNTHETIC	0.20	£9.50	£5.06	£1.01	2128722	OIL FILTER	1.00	£17.44	£8.63	£8.63	EOIL	F 913D 5W/30 ENGINE OIL	6.10	£9.95	£5.95	£36.30
Item	Person	Rate	Qty	Total																																																														
Carried Out Vehicle Identity Check Including Print of VIN &	Darrel J	65.00	0.40	£26.00																																																														
PDI	Darrel J	65.00	2.00	£130.00																																																														
SERVICE	Darrel J	65.00	0.50	£32.50																																																														
VHC	Darrel J	0.00	0.30	£0.00																																																														
MOT Labour	Mike E	65.00	0.75	£0.00																																																														
Carried Out MOT Test	Mike E	65.00	0.8	£0.00																																																														
Part Number	Description	Qty	Retail	Price	Total Price																																																													
	#NPANST6269 TIE ROD END	1.00		£17.53	£17.53																																																													
SX75/90	GEAR OIL SYNTHETIC	0.20	£9.50	£5.06	£1.01																																																													
2128722	OIL FILTER	1.00	£17.44	£8.63	£8.63																																																													
EOIL	F 913D 5W/30 ENGINE OIL	6.10	£9.95	£5.95	£36.30																																																													
Has the cam belt been changed? (5 years on all ford 2.0 and fiat 2.3)																																																																		
Cam belt change info																																																																		
Cam belt change invoice																																																																		
Habitation Service Reports																																																																		
Habitation service info																																																																		

CMS MOTORHOME INSPECTION FORM

Habitation service photos



Marquis Service
The UK's largest dealer network

	Date: 13.4.23	Job No. 33824
Cobles	Model: MARQUIS	Reg No or VIN: H615DKC
Serial No: 12680599	Mileage:	Next Habitation Inspection:

Marquis carry out Habitation Inspections and Repairs to both Touring Caravans and Motorhomes. All work is carried out in accordance with the current Approved Workshop Scheme Standards.

The following list is the breakdown of the areas that will be checked during the Habitation Inspection:

<input checked="" type="checkbox"/> Gas	<input checked="" type="checkbox"/> Appliances	<input checked="" type="checkbox"/> Damp Survey
<input checked="" type="checkbox"/> 12v Electrics	<input checked="" type="checkbox"/> Ventilation	<input checked="" type="checkbox"/> Brakes
<input checked="" type="checkbox"/> 230v Mains Electrics	<input checked="" type="checkbox"/> Fire Safety	<input checked="" type="checkbox"/> Wheels & Tyres
<input checked="" type="checkbox"/> Water System	<input checked="" type="checkbox"/> Bodywork	

IMPORTANT NOTICE

The Habitation Inspection does not include servicing of the base vehicle and road legal requirements. Appliances are checked for operation only, additional servicing may be required for warranty purposes.



APPROVED WORKSHOP
ncc




www.marquisleisure.co.uk

CMS MOTORHOME INSPECTION FORM

In receiving this form you are automatically agreeing with this acknowledgment. Whilst it would be nice to have a full AA style report and professional habitation check, it is not realistic and we are not trained to do so, so take all descriptions & reports as the assessors opinion only. All of our listed checks were opinion of the assessor before the date of the auction, conditions of the motorhome or caravan are expected to change in that time. Take into consideration fair wear and tear for the age of the motorhome. We do not test heating, gas, electric, water systems or accessories. All motorhomes are driven to the auction unless stated. MOT history & mileage checks are public record for the buyer to do their basic due diligence with. This is a trade auction only and must be treated as such. Bidding is bound by British Car Auction terms and conditions. Please visit <https://www.bca.co.uk> for auction terms and conditions. Bid at your own risk.