

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Concorde Credo i735H
Reg Number - NO GAP	AGO2BED
HPI Clear	Yes
VAT	No
Engine Size	3.0
BHP	0
Transmission	Automatic
Miles or KM	Miles
Mileage	44000
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Drop Down Bed, Transverse Bed
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	No




CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Tow bar, Reversing camera, Air Suspension, Electric step, Solar panel, Tv Aerial
Decals	Need attention
Decals Further Info	Os slightly faded // ns peeling // rear streaky //



Any Damage Found	Yes
Damage Further Info	Scratch ns garage door // small cracks nsr wheel archer // crack ns passenger side // os front trim different colour // silicon loose ns window above cab //




+2 more photo(s) available

Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Tv(s), Oven, Carpets, Bluetooth, Auto wipers, cab A/C, Cab blinds, DAB radio, WIFI, Climate control
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Not original mattress on transverse bed



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	07/09/24
Cam belt changed	N/A
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	K4044
Completed by	Keenan Parnell
Sign-off Date	2025-09-02
Price Guide	N/A