

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Big Wave Campers
Reg Number - NO GAP	DG19HCC
HPI Clear	Yes
VAT	No
Engine Size	1.9
BHP	101
Transmission	Manual
Vehicle Weight (kg)	2800
Miles or KM	Miles
Mileage	83217
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No







Internal Layout



Does internal look original?	Yes
Berths	4
Belts	5
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Parking sensors, Front fog lights
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Stone chips on bonnet and drivers door // scratch on passenger door // chip on fuel flap // n/s a pillar chipped // sliding door scratches // n/s mirror damaged






Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Auto headlights, Bluetooth, cab A/C, Cruise control, DAB radio, Diesel heater, Heated mirrors, Leather, Multifunction steering wheel
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	RIP on drivers seat



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

