

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Starlight Conversion
Reg Number - NO GAP	EF68NVW
HPI Clear	Yes
VAT	No
Engine Size	2.0L
BHP	101
Transmission	Manual
Vehicle Weight (kg)	2600
Miles or KM	Miles
Mileage	69006
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	1
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Parking sensors, Solar panel
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Scratch to rear off side next to electric hook up



Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No


CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Auto headlights, Auto wipers, Bluetooth, cab A/C, DAB radio
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection



Damp (visible/soft)	No
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Last service photos
Cam belt changed	Yes
Cam belt info	Ganged in 20121
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-02-17

