

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Rapido 963F
Reg Number - NO GAP	FJ55ENN
HPI Clear	Yes
VAT	No
Engine Size	2.8
BHP	123
Transmission	Manual
Vehicle Weight (kg)	3850
Miles or KM	Miles
Mileage	21523
Confirm miles (within 5,000)	No
Is Mileage Warranted	Mileage Discrepancy
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	No
More Info	Power steering is low
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Overcab Bed, Transverse Bed
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM



Exterior Inspection

External Extras	Roof rack, Habitation door lock, Tow bar, Ladder, Reversing camera
Decals	Need attention
Decals Further Info	Ns slightly fading //



Any Damage Found	Yes
Damage Further Info	Both sing mirrors scuffed // scuff os front // bad repair os // nsr bumper cracked with scuff on light cluster //





Windscreen

Crack






Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection


Internal Extras	Cruise control, Multifunction steering wheel
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Missing mattress // sink silicone // tape on hab door //





Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Ns and os rear corners in garage both stained
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Latest: 17/08/2022
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	Latest: 10/08/2017

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Keenan Parnell
Sign-off Date	2026-04-14