

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Auto-Sleepers Nuevo ES
Reg Number - NO GAP	HF05HRW
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	101
Transmission	Manual
Vehicle Weight (kg)	N/A
Miles or KM	Miles
Mileage	38597
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Overcab Bed, Bench Seats
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	No

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Habitation door lock, Parking sensors, Tow bar, Satellite dome, Ladder
Decals	Good
Any Damage Found	Yes
Damage Further Info	N/s front bumper stress cracked // n/s rear light cluster not sitting in properly// both off side windows cracked // minor paint flake to drivers door // o/s front inner wing needs welding





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A


CMS MOTORHOME INSPECTION FORM


Internal Inspection

Internal Extras	Cab curtains, Heated mirrors, Oven, Upgraded stereo
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	N/s front corner wall to floor // damp and water marks to o/s front // damp floor to n/s rear under kitchen unit
Floor damp/spongy/damaged	No







CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	29-8-23
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	16-10-23



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Rodger Snell
Sign-off Date	2026-02-13