

CMS MOTORHOME INSPECTION FORM

General Information

| | |
|------------------------------|-----------------------------|
| Make & Model | Autotrail Frontier Savannah |
| Reg Number - NO GAP | WA60AMO |
| HPI Clear | Yes |
| VAT | No |
| Engine Size | 2.3 |
| BHP | 130 |
| Transmission | Manual |
| Vehicle Weight (kg) | 3500 |
| Miles or KM | Miles |
| Mileage | 39421 |
| Confirm miles (within 5,000) | Yes |
| Is Mileage Warranted | Yes |
| Engine Keys Count | 2 |
| V5 present | Yes |
| V5 VIN Match | Yes |

Engine Bay

| | |
|---------------------------|------|
| Fluid levels correct? | Yes |
| Oil/Coolant Contamination | No |
| Engine bay check | Pass |

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

| | |
|----------------------------|-----|
| Brake Pedal Pressure Pass | Yes |
| Handbrake Test Pass | Yes |
| Static Gear Selection Pass | Yes |
| Clutch Slip Test Pass | Yes |
| Steering Noise | No |
| Engine Noise | No |


Internal Layout

| | |
|------------------------------|--------------------------|
| Does internal look original? | Yes |
| Berths | 4 |
| Belts | 4 |
| Bed Options | Bench Seats, Single Beds |
| Lounge Layout | Bench Seats |
| Layout Correct | Yes |
| Further Comments | No |

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

| | |
|---------------------|---|
| External Extras | Gaslow, Awning, Alloys, Reversing camera, Ladder, Tow bar, Solar panel, Tv Aerial, LED daytime running lights |
| Decals | Need attention |
| Decals Further Info | Faded and cracked // missing lower decal to passenger door |



| | |
|---------------------|---------------------------|
| Any Damage Found | Yes |
| Damage Further Info | N/S/F corner light scrape |



| | |
|--------------|-----------|
| Windscreen | No damage |
| Alloy Wheels | |

| | |
|------------------------------------|---------------|
| Good | |
| Tyres illegal/cracking/out of date | No |
| Electric Step | Fully Working |
| Self levelling work | N/A |
| Pop top canvas damage | N/A |

CMS MOTORHOME INSPECTION FORM



Internal Inspection

| | |
|---------------------------|---|
| Internal Extras | cab A/C, Cab blinds, Cruise control, Oven, Upgraded stereo, Tv(s) |
| Other Extras | N/A |
| Electrics turn on | No |
| More Info | Needs new leisure battery |
| Control panel damaged | No |
| Stereo turn on | Yes |
| Smell or signs of smoking | No |
| Cushions correct | Yes |
| Boiler present | Yes |
| Overhead lockers ready | Yes |
| Internal Damage | Yes |
| Damage Info | Rust around hob |



Damp Inspection


| | |
|---------------------------|--------------------------|
| Damp (visible/soft) | Yes |
| Damp Info | Rear garage wall stained |
| Floor damp/spongy/damaged | No |



CMS MOTORHOME INSPECTION FORM

Paperwork

| | |
|----------------------------|---------|
| Manuals present | Yes |
| Engine Service History | Partial |
| Service Info | 15/8/23 |
| Cam belt changed | Yes |
| Cam belt info | 10/21 |
| Habitation service reports | Partial |
| Habitation Info | 08/25 |



Test Drive & Sign Off

| | |
|-------------------------------------|--------------|
| Test drive - 10 mins | Pass |
| Engine lights | No |
| Dashboard ghosting/Mileage flashing | No |
| V5 tested on DVLA | Yes |
| Completed by | Rodger Snell |
| Sign-off Date | 2026-01-26 |