

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Lunar Homecar 59
Reg Number - NO GAP	YN06PZS
HPI Clear	Yes
VAT	No
Engine Size	2.5
BHP	115
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	76518
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	French Bed
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM



Exterior Inspection

External Extras	Awning, Bike Rack, Reversing camera, Air Suspension, Tv Aerial
Decals	Good
Any Damage Found	Yes
Damage Further Info	NSR bumper cracked // paint delamination NSR wheel arch // stone chips front bonnet // dink NS panel // dink rear // NSF paint flake





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	Cracking ns front // crazing nsr // os front cracking



Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A



CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, Cab curtains, DAB radio, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection


Damp (visible/soft)	Yes
Damp Info	Pimpling under os window // boarded osr under garage locker door //
Floor damp/spongy/damaged	Yes
Floor Info	Soft floor in garage



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	No
Engine Service History	Partial
Service Info	19/02/26
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	28/06/2018



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Keenan Parnell
Sign-off Date	2026-03-27