

CMS MOTORHOME INSPECTION FORM

General Information

| | |
|------------------------------|----------------------|
| Make & Model | Autotrail Delaware S |
| Reg Number - NO GAP | K44OCO |
| HPI Clear | Yes |
| VAT | No |
| Engine Size | 2.3 |
| BHP | 150 |
| Transmission | Automatic |
| Miles or KM | Miles |
| Mileage | 16,865 |
| Confirm miles (within 5,000) | Yes |
| Is Mileage Warranted | Yes |
| Engine Keys Count | 2 |
| V5 present | Yes |
| V5 VIN Match | Yes |

Engine Bay

| | |
|---------------------------|------|
| Fluid levels correct? | Yes |
| Oil/Coolant Contamination | No |
| Engine bay check | Pass |

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

| | |
|----------------------------|-----|
| Brake Pedal Pressure Pass | Yes |
| Handbrake Test Pass | Yes |
| Static Gear Selection Pass | Yes |
| Clutch Slip Test Pass | Yes |
| Steering Noise | No |
| Engine Noise | No |

Internal Layout

| | |
|------------------------------|--------------------------|
| Does internal look original? | Yes |
| Berths | 2 |
| Belts | 3 |
| Bed Options | Single Beds, Bench Seats |
| Lounge Layout | Bench Seats |
| Layout Correct | Yes |
| Further Comments | No |

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

| | |
|-----------------|---|
| External Extras | Alloys, Gaslow, BBQ point, Awning, Tow bar, Reversing camera, Other, LED daytime running lights, Electric step, Solar panel, Automatic self levelling |
| Decals | Good |



| | |
|------------------|----|
| Any Damage Found | No |
|------------------|----|



| | |
|------------------------------------|-----------|
| Windscreen | No damage |
| Alloy Wheels | Good |
| Tyres illegal/cracking/out of date | No |
| Damp floor underneath | No |
| Electric Step | N/A |
| Self levelling work | No |
| Pop top canvas damage | No |

CMS MOTORHOME INSPECTION FORM

Internal Inspection

| | |
|---------------------------|--|
| Internal Extras | Alarm, Cruise control, Bluetooth, Cab blinds, Carpets, Sat nav, Traction control plus, Hill descent control, Multifunction steering wheel, Oven, Tv(s), WIFI |
| Other Extras | N/A |
| Electrics turn on | Yes |
| Control panel damaged | No |
| Stereo turn on | Yes |
| Smell or signs of smoking | No |
| Cushions correct | Yes |
| Boiler present | Yes |
| Overhead lockers ready | Yes |
| Internal Damage | No |

Damp Inspection

| | |
|---------------------------|----------------------------|
| Damp (visible/soft) | Yes |
| Damp Info | Blue staining os garage // |
| Floor damp/spongy/damaged | No |



CMS MOTORHOME INSPECTION FORM

Paperwork

| | |
|----------------------------|----------|
| Manuals present | Yes |
| Engine Service History | Full |
| Service Info | 19/01/24 |
| Cam belt changed | N/A |
| Habitation service reports | Full |
| Habitation Info | 23/01/25 |



Test Drive & Sign Off

| | |
|-------------------------------------|----------------|
| Test drive - 10 mins | Pass |
| Engine lights | No |
| Dashboard ghosting/Mileage flashing | No |
| Cruise control comment | N/A |
| V5 tested on DVLA | Yes |
| All stages completed | Yes |
| Trade plate number | K4044 |
| Completed by | Keenan Parnell |
| Sign-off Date | 2025-11-25 |
| Price Guide | N/A |