

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Autocruise Pioneer Diaz
Reg Number - NO GAP	KE53NYU
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	85
Transmission	Manual
Miles or KM	Miles
Mileage	51384
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	No

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Habitation door lock, Tow bar, Awning
Decals	Need attention
Decals Further Info	Above cab faded // peeling rear // faded ns //



Any Damage Found	Yes
Damage Further Info	Dink passanger door // ns wing slightly scuff // delamination os // osr slight crazing // osr lower crazing // missing nsr reflector // Rust on tow bar



+2 more photo(s) available

Windscreen	Chip(s) smaller than 10p
------------	--------------------------




Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM


Internal Inspection

Internal Extras	Carpets, Cab curtains, Cruise control, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Wood peel os above bench seats



Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Ns behind bench seat blue staining
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	13/07/10
Cam belt changed	No
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	Yes
Engine Lights Info	Service warning light
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	K4044
Completed by	Keenan Parnell
Sign-off Date	2025-09-11
Price Guide	N/A